

# PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

## PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School Sri chaitanya Techno School
2. Location Eldeco Greens, Nakodar Road, Jalandhar
3. Plot Area 3.14 acres
4. Plinth Area (16940 + 16208 + 2770) = 35918 Sq. ft.
5. Number of Storey's Ground / First / Second
6. Year of Construction of Building 2015
7. **If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given**
  - a) Name of the Engineer with qualification Yes, SS Bhatia, G.D Arc. B-2 Vivek Vihar Delhi,
  - b) Address of Engineer The Building was
  - c) Set of Structural drawings used in the construction, if available Constructed by the above
  - d) Name & address of Architect with qualification Architect
8. **Whether the building has been constructed for the purpose**
  - a) School SS Bhatia G.D Arc. M.C.B-2 vivek vihar Delhi
  - b) Residential Purpose and converted for use as a School YES/ NO
9. **Materials used for roofs**
  - a) R.C.C. Slabs/R.B.C. Slabs YES/ NO
  - b) R.S. Joist & Battens YES/ NO
  - c) Wooden joists & Battens YES/ NO
10. **Materials used for walls**
  - a) Mud Mortar YES/ NO
  - b) Cement Mortar YES/ NO
  - c) Lime Mortar YES/ NO
11. **Flooring**
  - a) Conglomerate YES/ NO
  - b) Terrazzo YES/ NO
  - c) Brick Paving YES/ NO
12. **A detailed drawing indicating dimensions of the rooms Along with size and location of doors and windows (Attached)**

**Sri Chaitanya Techno School**  
**Eldeco Greens,**  
**Jalandhar City-144026**

Signature with Stamp of the seal  
 Of the School/Institution

Name of the School:- Sri Chaitanya Techno School,  
Nakodar Road, Jalandhar

**PART-II**

( To be filled by the S.D.E.)

No. 17

Dated 26/04/22

- a) I have visited the above mentioned school on dated 26-04-2022.... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) 31-03-2023.

*I have visited the School  
Building the Building visually & ok*

*V  
A/E*

*Recommended*

*[Signature]*  
Sub Divisional Engineer  
Constn S/D 3, PWD B&R Br.  
Jalandhar Cantt.