

GOVERNMENT OF ANDHRA PRADESH
ROADS & BUILDINGS DEPARTMENT

From:
Sri A.D.D.Samarpana Rau, B.Tech.,
Executive Engineer,
(R&B) Division,
Guntur.

To:
The Principal,
Sri Chaitanya School,
Inner Ring Road,
Reddypalem,
Guntur.

Letter No. Soundness Certificate /JTO-1 / 2021-22, Dated: 30.12.2021.

Sir,

Sub:- (R&B) Division, Guntur – Structural Soundness Certificate – Building of *Sri Chaitanya School, Inner Ring Road, Reddypalem, Guntur* - Report -
Furnished — Regarding.


Ref:- 1) Letter No.NIL, dated: 06.12.2021 of the Sri Chaitanya School, Inner Ring Road, Reddypalem, Guntur.
2) Letter No.Soundness certificate/HC/2021, Dt: 28.12.2021, of the Deputy Executive Engineer (R&B) Special Sub-Division, Guntur.

----- @@@ -----

With reference to the above, the Deputy Executive Engineer, (R&B) Special Sub-Division, Guntur has personally inspected the "*Sri Chaitanya School, Inner Ring Road, Reddypalem, Guntur*" on 27.12.2021 which was located opposite to Agatavarappadu road, near Bhagat Singh Statue, Inner Ring Road, Reddypalem, Guntur bearing Door No.327/P & 326/P. The building is RCC framed structure with G+4 floors.

On visual observations, it is observed that the above said building is *Structurally sound as on this date.*

Yours sincerely

For 
Executive Engineer
(R&B) Division, Guntur
30/12/2021