

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 15.12.2023

It is certified that the existing building **SRI CHAITANYA SCHOOL** .(name of the building or premises) at **INNER RING ROAD REDDYPALEM, GUNTUR.** (address) is having block(s)/Floor(s) as per details below:

Detail Of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the school	4					

The building is owned/occupied by **Sri Chaitanya School** (Name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Roads & Buildings Department** (Name of Department/ Govt.) on **04.12.2023** (date of inspection) in the presence of **V. VENKATESWARA RAO** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **04.12.2023** ... for a period of **1** years in accordance with rule and subject to compliance of the specific conditions as appended.

1.

2. — NIL —

3.

4.

Issued on **15.12.2023** at **Guntur** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Signature with Seal

Name

Designation:

Name & Address of Department/Office

As per 15/12/23
EXECUTIVE ENGINEER
(R&B) DIVISION
GUNTUR