

Translated from Kannada Origin into the English Language

Office of the Assistant Executive Engineer,
No.1 Building's Sub Division, VV Kendra,
Bengaluru

DEPARTMENT OF PUBLIC WORKS

No.AEE/No.1.A.S.D/A.E-1/2023-24/786

Date: 02/12/2023

To,
The Principal,
Sri Chaitanya Techno School,
No. 136/1, Kaggadasapura Main road,
Near Vignan Nagar bus stop, Bangalore 560075

Dear,

Sub: reg. issuance of building safety certificate to Sri Chaitanya Techno School,

Ref: 1) Sri Chaitanya Techno School, Bengaluru, letter dated: 23-11-2023

2) Govt. Order No.PWD/59/B.E.D/2019/Dated: 06/05/2022.

&&&

With subject to the above matter, Sri Chaitanya Techno School, Survey No. 825, no. 136/1, Kaggadasapura Main road, Near Vignannagar bus stop, Bangalore 560075 is requested in their letter of reference (1) to issue building safety certificate stating that the certificate is required for educational purposes and the documents related to the said building has been submitted to this office.

Accordingly, in the presence of the Principal, the school building Sri Chaitanya Techno School on 01-12-2023 has been reviewed and as per the order of the Government of reference No.(2) to grant school's safety certificate in the city area you have submitted D.D. to this office drawn in favour of the Assistant Executive Engineer, No. 1 Buildings Sub-division, V.V. Centre, Bangalore for Rs. 5000/- drawn on Axis Bank's DD. No: 013300/ Dated: 28-11-2023.

The school building complex consists of 01 Manager's Room, 01 Emergency Treatment Room, Reception Hall, 02 Store Room, 01 Guest Room, 01 Electrical Room, 10 classrooms on the ground floor. There are separate toilets for staff, boys and girls. There are 08 classrooms on the first floor and 01 AV room. 02 staff room, 01 hall: 01 computer lab, separate toilet for staff and girls. There are 16 rooms on the second floor. There will be separate toilets for staff and girls. The third floor has 16 rooms with separate toilets for staff and boys.

- Whereas the said building found constructed on the Sri Chaitanya Techno School, Survey No. 825, no. 136/1. Kaggadasapura Main Road, Near Vignan Nagar bus stop, Bangalore 560075 and the ownership of said building is in the name of Hayagriva Educational Trust Bangalore.



P.G. SREEDHARA
TRANSLATOR
Om Nivasa

Translated from Kannada Origin into the English Language

- Regarding concrete strongness of building pertaining to Building safety, on 18-11-2023 M/s. Sree Tech Supports, 1st Main, 10th Cross, Doddabettahalli Layout, Vidyananyapura Post Bangalore 560097 have conducted Rebound hammer test & Ultra Sonic test and submitted the report.
- Annexure-1 to 6 is submitted.

After go through and verify all the documents submitted by the aforesaid institution, have also conducted Safety Check report, Physical observation, Investigating studies, Rebound hammer test, Ultra Sonic test report, Ultra Sonic pulse velocity test and M/s Sree Tech Supports Bangalore have given a certificate that the building is structurally safe. The said reports and the building were inspected and R.C.C. of the building No cracks were found in the pillars, beams and Roof/Chavani and the building was found to be apparently safe. And since the test reports have found that the building is in Structural Sound Condition and the building is apparently safe. The following conditions are suggested to be followed.

1. shall get Permission from the competent authorities of fire department and other concerned departments/the certificate should be obtained within the stipulated time as per the rules.
2. shall carry Systematic maintenance of the building from time to time by experts using high quality materials.
3. Safety of students and teachers should be given priority and appropriate safety system should be adopted.
4. No other works which may affect the integrity of the building shall be carried out without the permission of the competent authority. If done without permission, the certificate will expire immediately.
5. Drinking water and toilets should always be kept clean and all directives and regulations related to schools and colleges should be compulsorily followed by the Bruhath Bengaluru Mahanagara Palike.
6. There are cracks in the walls of the head room in place of the terrace, repair them and paint the cracks in some parts of the ceiling by water proofing.

Subject to the aforesaid terms and conditions Building Safety Certificate issued to the building Sri Chaitanya Techno School, Survey No. 825, No 136/1, Kaggadasapura Main road, Near Vignan nagar bus stop Bangalore - 560075

Yours Sincerely

Sd/-

AEE,

NO.1, Building's Sub-Division,
VV Kendra, Bengaluru

Translated from Kannada Origin into the English Language

P.G. SREEDHARA
TRANSLATOR

Om Nivas, 3rd Main 2nd Cross,
Panathur Dinne, Panathur Post
Bangalore - 560103.
Mob: 9449643940

ATTESTED
L. GOPALAKRISHNA, B.A.
ADVOCATE & NOTARY
GOVERNMENT OF INDIA
No.25, 3rd Cross, Lalbagh Road
BANGALORE - 560024

29 APR 2024

