

To


The Principal,

Sri Chaitanya Techno School,

Sy No. 84/3, 84/4, Horemavu Village,

K R Puram Hobli,

Bangalore.



Subject: Issuance of Building Safety Certificate

Reference:

1. Letter from Sri Chaitanya Techno School, Bangalore Dated: 05-04-2023
2. Government Order No: L..E/59/B.E.D/2019/Dated: 06-05-2022


Dear Principal.


Regarding the above matter, Sri Chaitanya Techno School, Sy No. 84/3,84/4, Hormavu Village, K R Puram Hobli, Bangalore, has requested in their letter of reference (1) to issue a Building Safety Certificate. They are required to provide this certificate for educational purposes, and the related documents have been submitted to this office.

Accordingly, the school building was inspected on 15-04-2023 in the presence of the Principal of Sri Chaitanya Techno School and the Assistant Executive Engineer, No. 1 Buildings Sub- division, V. V Centre, Bangalore. A payment of Rs. 5000/- via Axis Bank's DD No: 118061, dated 13-04-2023, has been submitted to this office.

The School building complex includes one office, one principal room, one Activity room, Infirmary room 12 classrooms on the ground floor, with separate toilets for boys and girls. Three upper floors with library, Labs & 44 Classrooms. The building is owned by Nexgen Educational Trust, Bangalore, and was constructed in the year 2022-23.

The building's concrete strength has been assessed through a Rebound Hammer Test and Ultra Sonic Test Conducted by M/s. Sree Tech Supports, Bangalore. These tests, along with annexures 1 to 6, have been submitted for review. All documents provided by organization have been checked, and a comprehensive safety check, including physical observations and investigating studies, was undertaken. M/s. Sree Tech


Manager
Sri Chaitanya Techno School
Bangalore


SRI CHAITANYA TECHNO SCHOOL
Sy. No. 84/3, 84/4,
Horemavu Main Road
Horemavu, Bangalore East - 560 043

Supports, Bangalore, has certified the building as structurally safe. No cracks were found in the pillars, beams, and roof, and the building was deemed apparently safe.


Since the test reports have confirmed the building is in a structurally sound condition, the following conditions are suggested to be followed:

1. Obtain permission from the competent authorities of the fire department and other concerned departments within the stipulated time as per the rules.
2. Conduct systematic maintenance of the building from time to time by experts using high-quality materials.
3. Prioritize the safety of students and teachers and adopt an appropriate safety system.
4. Avoid any works that may affect the integrity of the building without obtaining permission from the competent authority. If such works are done without permission, the certificate will be cancelled immediately.

Based on these findings, a Building Safety Certificate for Sri Chaitanya Techno School, Sy No. 84/3,84/4, Horamavu Village, K R Puram Hobli, Bangalore, is issued.

Yours faithfully,
Assistant Executive Engineer
No. 1 Buildings Subdivision, Bangalore.

TRUE TRANSLATION FROM
KANNADA TO ENGLISH



ATTESTED
K.B. SADHA SHIVAPPA B Com L L B
ADVOCATE & NOTARY PUBLIC
GOVERNMENT OF INDIA
#15, Sagar Nilaya, Sri Venkateshwara Theatre Road
2nd Cross, Nethravathi Layout, Devasandra
K.R. Puram BANGALORE -560 036

Chaitanya Techno School
Manager
Bangalore

13 JUL 2024