

Public Works Department

From

Er.A.Valluvan,B.E.,M.E.(Struct),
Superintending Engineer, PWD,(I/C)
Buildings (C&M) Circle, Trichy-1
Phone : 04312462604,
Email:sebuildings_trichy@yahoo.com

To

Principal
Sri Chaitanya Techno School,
No.1, Kumaran Road ,
Senthaneerpuram,
Trichy

Letter No. F-14/DB/DO/2023/Date: 30.06.2023

Sir,

Sub: Buildings – Structural Stability Certificate for **Sri Chaitanya Techno School, No.1, Kumaran Road , Senthaneerpuram, Trichy** - Structural Stability issued- - reg.

Ref: 1. G.O. Ms. No.231 / Municipal Administration and water supply Department, date.24.09.1996.

2. Chief Engineer, PWD, Trichy Region, Trichy, Lr.No.AEE T1/F. Stability / 2023/Date:30.06.2023.

With reference to the above letter cited, I enclose herewith the Structural Stability Certificate for **Sri Chaitanya Techno School, No.1, Kumaran Road , Senthaneerpuram, Trichy** for taking further action.

Encl: Structural Stability Certificate.


Superintending Engineer, PWD,(I/C)
Buildings (C&M) Circle, Trichy-1


30.6.23

**OFFICE OF THE SUPERINTENDING ENGINEER, PWD.,
BUILDINGS CONSTRUCTION & MAINTENANCE CIRCLE, TRICHY**

FROM E

From of report to be made to the competent Authority be inspecting authorities or officers appointed under section 28 of the Madras Public (Licensing) Act 1965 (Madras Act 13 of 1965) referred in rule 7 of the Madras Public Buildings (Licensing) Rule 1966

1	Name of the Designation of Inspecting authority or officer appointed or having jurisdiction under any other act of Law	Superintending Engineer, PWD ,(I/c) Buildings C&M Circle, Trichy-1
2	Location of the building inspected (Door No Street No Name of Place i.e Municipal corporation / Municipality / Panchayat or Panchayat Union / Township / Contonment	Sri Chaitanya Techno School, No.1, Kumaran Road , Senthaneerpuram, Trichy Old Survey No: 103 / 1B ,104 /2 , 108 /1C , 108/ 2A3, Ward V , Block 14 & New T.S No:4
3	Date of Inspection	28.06.2023
4	Purpose for which the building is used	Education (School Building)
5	Nature of defects noticed	NIL
6	Suggestions for rectifying defects	NIL
7	If in a dangerous condition immediate steps recommended to be taken	NIL


**Superintending Engineer, PWD, (I/c)
Buildings C&M Circle, Trichy-1**

8.7/30.6.23

**OFFICE OF THE SUPERINTENDING ENGINEER, PWD.,
BUILDINGS CONSTRUCTION & MAINTENANCE CIRCLE, TRICHY**

From of opinion under sub- section (1) of section 28 of the Madras Public Building (Licensing) ACT 1965 (Madras ACT 13 of the 1965 referred to in rule 7 of the Madras Public building (Licensing) Rules 1966)

I have inspected the building specified in the statement below assuming the building has been constructed as per the structural design furnished by the private chartered Engineer **S.Ramalingam, Class - 1A Engineer, Trichirapalli District, (Dt/18918/2015), 12, southkandi street, bemma Nagar, Trichy.** I have come to an opinion that the building is structurally sound to be used as a public Building for the purpose specified in the statement. The structural soundness of the building has been verified taking into account the loading as per the latest Indian Standards 875. I am therefore of the opinion that a license may be granted for the period from **01.04.2023 to 31.03.2026.**

STATEMENT TO ACCOMPANY THE OPINION REGARDING STRUCTURAL SOUNDNESS

Location of the Building (Door No. Street No. Name of the Place :		Sri Chaitanya Techno School, No.1, Kumaran Road , Senthaneerapuram, Trichy					
		Built-up area	Age of the Building	Purpose for which the building can be used	The Period for which the building will be structurally sound	Number of persons to be accommodated	Remarks
Ground Floor		2017.78 M ²	3 years	Education (School Building)	01.04.2023 to 31.03.2026..	2500 Persons	
First Floor		1631.37 M ²					
Second Floor		1732.94 M ²					
Third Floor		1732.94 M ²					
Total		7115.03 M ²					


 Superintending Engineer, PWD, (I/c)
 Buildings C&M Circle, Trichy-1
 20.06.23