

PART - I
PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/ Institution)

- 1 (a) Name of the school : SRI CHAITANYA TECHNO SCHOOL
(b) Level/Standard of School:- : CBSE - 1631119
© Whether School is affiliated to C.B.S.E. or P.S.E.B. if affiliated then affiliation No. : Eldeco Greens, Nakodar Road
- 2 Location : Jalandhar
- 3 Plot Area : 3.14 Acre
- 4 Plinth Area : (16940 + 16200 + 2770) 35910 sqft
- 5 Number of Storey : Ground / First / Second
- 6 Year of construction of building. : 2015
- 7 If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given.
 - a) Name of the Engineer with Qualification : S.S. Bhatia, G.D. Arch M/C
 - b) Address of the Engineer : B2 Vivek Vihar Delhi
 - c) Detail of structural drawings used in the construction. : The building was constructed by the Above architect
 - d) Name & Address of Architect with qualification. : S.S. Bhatia, G.D. Arch M/C
- 8 Whether the building has been constructed for the purpose of
 - a) School : Yes
 - b) Residential purpose and converted for use as a school. : NO
- 9 Material used for roofs
 - a) R.C.C. slabs : Yes
 - b) R.S. Joists & Battens : Yes
 - c) Wooden Joints & Battens. : Yes
- 10 Material used for walls
 - a) Mud mortar : No
 - b) Cement mortar : Yes
 - c) Plaster
 - i) Lime mortar : No
 - ii) Cement mortar : No
- 11 Flooring :-
 - a) Conglomerate : Yes
 - b) Terrazo : Yes
 - c) Brick paving : Yes
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. : Attached
- 13 Whether fire safety certificate obtained from concerned fire officer. : Yes
- 14 It is also certified that there is no any court case or stay is pending regarding this building in any Hon'ble Court. : Yes

Signature and Stamp of the Head
of the School

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE

(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)

Name of the School: SRI CHAITANYA TECHNICAL SCHOOL
Eldeco Greens, Jalandhar,

- 1) This office Assistant Engineer/Junior Engineer visited the above mentioned - School on 08-06-2024 and have visually inspected it for its safety and find it fit for normal use as a school building.
- 2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used)

2024-25 (up to 31-03-2025)

Ref. No. 47

Dated 14/6/2024

Kalinder Singh

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,

ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੋ.ਨਿ.ਵਿ.ਡ ਤੇ ਮ.ਸ਼ਾਖਾ,

ਜਲੰਧਰ ਡਾਇਰੀ

E-Challan - 12004863

Date - 14/6/2024

Amount. - 10,000/-